#### **Audit Photo Report**

R-Cloud- 25041675





Factory entrance







Suggestion box





Attendance machines

**BSCI COC POSTED** 





Drinkable water supply

Eye wash station





Exit sign and emergency light


Ladder in injection section installed with handrail





Fire hydrant and extinguishers

Fire alarm





Evacuation plot plan

First aid kit





Fire hydrant testing Toilet

QIMA-QR-16-01B ©2025 QIMA Limited. Page 3 of 5

# **QIMA** Audit Photo Report 2025





Injection section


Silk printing section






Assembly section

packing section





NC 6.2 Attendance records sample

Payroll records sample





**CSR** policies

Electrician certificate





NC 7.7 Chemical missing secondary containment

NC 7.11 Materials leaned against the wall



NC 7.13 Electrical control panels missing inner insulation cover and switches not labelled

N/A

QIMA-QR-16-01B ©2025 QIMA Limited. Page 5 of 5